

1/7




FIG. 1




FIG. 2

2/7




FIG. 3




FIG. 4

3/7




FIG. 5




FIG. 6

4/7





FIG. 7A

5/7

LOCATE THE UPPER AND LOWER WIRES:



* - if required mandibular distalization > 4mm then
molar movement is not possible

FIG. 7B

6/7




FIG. 8




FIG. 9

7/7




FIG. 10




FIG. 11